

6/045,054

## WEST Search History

Hide Items

Restore

Clear

Cancel

DATE: Friday, August 05, 2005

Hide?	Set Name	Query	Hit Count
		<i>DB=PGPB,USPT; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L62	161 or 160	340
<input type="checkbox"/>	L61	148 not 160	86
<input type="checkbox"/>	L60	159 or 145	254
<input type="checkbox"/>	L59	L58 not 145	199
<input type="checkbox"/>	L58	corrosion and L57	219
<input type="checkbox"/>	L57	148 or L56	390
<input type="checkbox"/>	L56	146 and ((zn or zinc) adj5 (coating or film or layer))	265
<input type="checkbox"/>	L55	(heat or baking or baked or heated or heating) and L53	338
<input type="checkbox"/>	L54	(heat or baking or baked or heated) and L53	334
<input type="checkbox"/>	L53	148 or L52	365
<input type="checkbox"/>	L52	L51 not 145	214
<input type="checkbox"/>	L51	149 and L50	221
<input type="checkbox"/>	L50	146 and silane	597
<input type="checkbox"/>	L49	146 and corrosion	895
<input type="checkbox"/>	L48	L47 not 145	168
<input type="checkbox"/>	L47	141 and L46	186
<input type="checkbox"/>	L46	(((((zn or zinc) and paste and flake) or "zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer))	3166
<input type="checkbox"/>	L45	144 or 142	55
<input type="checkbox"/>	L44	L43 not 142	25
<input type="checkbox"/>	L43	(((((zn or zinc) and paste and flake) or "zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer)).clm.	55
<input type="checkbox"/>	L42	((("zinc flake" or "zinc alloy flake" or "zn flake" or "zn alloy flake") and (coating or film or layer)).clm.	30
<input type="checkbox"/>	L41	(106/1.17 or 106/14.05 or 106/14.39 or 106/403 or 428/401 or 428/389 or 428/397 or 428/381 or 428/583 or 428/659 or 427/123 or 427/372.2 or 427/375 or 427/376.6 or 427/376.7 or 427/376.8 or 427/383.1 or 427/383.7 or 427/384 or 427/388.1 or 427/404 or 427/405 or 427/406 or 427/430.1 or 427/435 or 427/436)! [CCLS]	15039
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L40	L39 not 138	10
<input type="checkbox"/>	L39	("zn flake" or "zn alloy flake") and (coating or film or layer)	13

<input type="checkbox"/>	L38 ("zinc flake" or "zinc alloy flake") and (coating or film or layer)	32
	<i>DB=PGPB,USPT,EPAB,JPAB; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L37 L36 and @pd > 20050412	9
<input type="checkbox"/>	L36 L35 and @pd>20041026	27
<input type="checkbox"/>	L35 L33 or L22 or L17 or L19	325
<input type="checkbox"/>	L34 L33 and @pd>20041026	20
<input type="checkbox"/>	L33 L28 or L29 or L30 or L31	162
<input type="checkbox"/>	L32 L31 and @pd > 20041026	9
<input type="checkbox"/>	L31 L30 and @pd > 20040708	12
<input type="checkbox"/>	L30 L27 not L28	54
<input type="checkbox"/>	L29 L27 notL28	108
<input type="checkbox"/>	L28 L25 or L26	108
<input type="checkbox"/>	L27 ((zinc adj2 alloy) and (zinc adj3 flake))	108
<input type="checkbox"/>	L26 "zinc alloy flake"	13
<input type="checkbox"/>	L25 (zinc adj3 flake) and paste	104
<input type="checkbox"/>	L24 stapa 4znaL7	117
	<i>DB=USPT,PGPB,JPAB,EPAB; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L23 L22 and @pd > 20040105	1
<input type="checkbox"/>	L22 L19 or L21	26
<input type="checkbox"/>	L21 L20 not L17	3
<input type="checkbox"/>	L20 ((zinc or zn) adj4 alloy) and ((zinc or zn) adj4 flake)	135
<input type="checkbox"/>	L19 L18 not L17	23
<input type="checkbox"/>	L18 (zinc adj4 pulver\$) and (cure or cured or curing)	32
<input type="checkbox"/>	L17 L15 or L16	278
<input type="checkbox"/>	L16 L14 not L15	75
<input type="checkbox"/>	L15 L10 or L11	203
<input type="checkbox"/>	L14 (zinc adj4 flake) and (cure or cured or curing)	195
<input type="checkbox"/>	L13 L11 not L12	65
<input type="checkbox"/>	L12 (cure or curing or cured) and L11	23
<input type="checkbox"/>	L11 L9 not L10	88
<input type="checkbox"/>	L10 L3 or L5 or L6 or L7 or L8	115
<input type="checkbox"/>	L9 (zinc adj4 alloy) and (zinc adj4 flake)	130
<input type="checkbox"/>	L8 "zinc alloy flake"	13
<input type="checkbox"/>	L7 L6 not L3	5
<input type="checkbox"/>	L6 ("lamellar zinc") and (cured or curing)	10
<input type="checkbox"/>	L5 4026710[uref]	7
<input type="checkbox"/>	L4 4620873[uref]	0
<input type="checkbox"/>	L3 ("zinc alloy flake" or "zinc flake") and (cured or curing)	96

<input type="checkbox"/>	L2	("zinc alloy flak" or "zinc flake") and (cured or curing)	94
<input type="checkbox"/>	L1	((428/401  428/389  428/397  428/381)!.CCLS.  (106/1.17  106/14.05  106/14.39  106/403)!.CCLS.  (or/)!CCLS.)	4034

END OF SEARCH HISTORY